

# Technical Service Bulletin

<b>COMPLIANCE:</b>	SUGGESTED
<b>SUBJECT:</b>	Reported case of water intrusion
<b>AFFECTED UNITS:</b>	GPS-NEMA4-OE Shipped after 11/23/2020
<b>DESCRIPTION:</b>	There has been a reported case of water entry past the door gasket on a GPS-NEMA-4-OE. This could result is a possible shock hazard and equipment damage.

## ACTIONS

- Inspect the position of the two enclosure latches. These should be turned a full 180 degrees and pushed down to seal the unit. Inspect the door gasket and mating surface for any damage or defects.
- Make sure the gasket makes contact with the mating surface when closing the door.
- Inspect the interior of the GPS-NEMA4-OE for water and evidence of past water intrusion.
- Ensure none of the components have been exposed to water. If evidence of water intrusion is found, Disconnect power to the GPS-NEMA4-OE and contact GPS for further instructions.

## ADDITIONAL COMMENTS

Contact GPS at [info@globalplasmasolutions.com](mailto:info@globalplasmasolutions.com)



[www.globalplasmasolutions.com](http://www.globalplasmasolutions.com)